TROPICAL ATMOSPHERE-OCEAN (TAO) PROGRAM FINAL CRUISE REPORT

RR-16-01

Area: Equatorial Pacific: 8°N 165°E to 8°S 165°E and 8°S 180° to 8°N 180°

Itinerary:

RR-16-01 DEP July 3, 2016, Apra Harbor, Guam

ARR August 5, 2016, Honolulu, HI

CRUISE DESCRIPTION

The Tropical Atmosphere Ocean (TAO) array consists of 70 buoys utilizing a taut line mooring configuration used to mount data collection sensors for climate research purposes. Fifteen buoys are serviced by JAMSTEC and the remaining 55 buoys from 95°W longitude to 165°E longitude are serviced by National Data Buoy Center (NDBC). Repair and maintenance of the buoys is performed by NDBC contracted personnel on an annual basis utilizing the NOAA Ships and other contract vessels.

NDBC Points of Contact

NDBC Operations Branch Chief NDBC Operations Manager

Bill Hansen Jeff Jenner

National Data Buoy Center National Data Buoy Center

Building 3205 Building 3205

Stennis Space Center, MS 39529 Stennis Space Center, MS 39529

228-688-3804 228-688-2784

Email: bill.hansen@noaa.gov Email: jeff.jenner@noaa.gov

TAO Cruise Objective and Plan:

The objective of this cruise was the maintenance of the TAO Array along the 165°E and 180° meridians. Dart station 52406 was also turned around on this cruise. In addition to regular operations, drifting Weather buoy 51001 and 51002 were recovered.

The scientific complement for the cruise embarked at Apra Harbor, Guam on July 3, 2016. The ship departed on July 3, 2016 and conducted operations as listed in Section 2.1. The ship arrived at Honolulu, HI on August 5, 2016.

1.0 **PERSONNEL**

1.1 <u>CRUISE LEAD AND PARTICIPATING SCIENTISTS</u>:

Cruise Lead: Brian Lake

Participating Scientists:

Name	Gender	Nationality	Affiliation
Brian Lake	M	US	NOAA/NDBC
James Rauch	M	US	NOAA/NDBC
Edward Kendrick	M	US	NOAA/NDBC
James Turner	M	US	NOAA/NDBC
Sophia Montalvo	F	US	NOAA/NDBC

2.0 **OPERATIONS**

2.1 <u>TAO Data Recovery Summary</u>

Mooring Operations conducted are shown in the tables below. The following provides details on the data recovery efforts for the buoys serviced. All noted times in this summary report are Coordinated Universal Time (UTC):

Cruise Summary

Buoy Site: 8N 165E				
Mooring Operation: Recovery		Mooring ID#: DM106		
Deployed Location: 08-04.11N/165-09.18E		Deployed Date: 10/31	Deployed Date: 10/31/14	
Recovered Location: 08-02.11N/165-08.88			16	
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: SSC, T25 fouled with sea growth				
Fishing/Vandalism: Longline on topsection socket, top section severed.				
General Comments: None				
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service	
			Observations	
SSC	4/28/16	Data low	Fouled- Growth	

Buoy Site: 8N 165E	Mooring Depth: 5226 m
--------------------	------------------------------

Mooring Operation: Deployment	Mooring ID#: DM190	
Deployed Location: 08-02.74N/165-08.54E	Deployed Date: 7/8/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 5N 165E				
Mooring Operation: Recovery		Mooring ID#: DM10	Mooring ID#: DM105	
Deployed Location: 05	-02.50N/164-50.21E	Deployed Date: 7/8/3	Deployed Date: 7/8/16	
Recovered Location: 05-02.15N/164-52.31E		Recovered Date: 7/8	Recovered Date: 7/8/16	
Sensors/Equipment Lo	st at Sea: None			
Sensors Damaged/Foul	led: SSC, T25, T50 fould	ed with sea growth		
Fishing/Vandalism: No	one			
General Comments: N	one			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service	
			Observations	
RH	4/20/15	Saturated		
1m Salinity	6/10/15	Low	Fouled, Top section	
			severed	
AT	5/30/15	Erratic		

Buoy Site: 5N 165E	Mooring Depth: 4769 m	
Mooring Operation: Deployment	Mooring ID#: DM191	
Deployed Location: 05-02.96N/164-51.99E	Deployed Date: 7/9/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 2N 165E			
Mooring Operation: R	Recovery	Mooring ID#: DM104	
Deployed Location: 02	2-00.75N/165-07.80E	Deployed Date: 10/29/14	
Recovered Location: I	Recovered Location: Drifting Recovered Date: NA		
Sensors/Equipment Lost at Sea: Drifting			
Sensors Damaged/Fouled: NA			
Fishing/Vandalism: Entire mooring Lost at Sea.			
General Comments: Acoustic release found horizontal on sea floor.			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations

RH	12/26/15	Data high	
1m Salinity	1/1/16	Data low	
Hull/ Mooring	1/31/16	Adrift	

Buoy Site: 2N 165E	Mooring Depth: 4168 m	
Mooring Operation: Deployment	Mooring ID#: DM192	
Deployed Location: 02-00.00N/165-08.01E		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 0 165E Flux/CO2		
Mooring Operation: Recovery	Mooring ID#: DM103	
Deployed Location: 00-01.38N/165-01.56E	Deployed Date: 10/27/14	
Recovered Location: 00-02.88N/164-57.60E	Recovered Date: 7/11/16	
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: SSC, TC5, TC10 fouled with sea growth, SSC connector broken,		
TC5 conductivity cage held on by one screw.		
Fishing/Vandalism: None		

General Comments: Top section severed, TP500 slid down wire to 700 m.			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations
Velocity at 50m	10/28/14	Bad. Not released	
TP500	7/6/15	Sensor slipped	Slid to 700m
RH	10/15/15	Data high	
Rain	11/10/15	Data missing	
1m,5m,10m,100m	1/30/16	Erratic/ low	Fouled, Connector
Salinity			broke
Inductive sensors	5/24/16	All missing	Downloads- "No
			Comms"
125m, 100m Salinity	1/9/15	Data failed	
Velocity at 10m	1/18/15	Data failed	

Mooring Depth: 4414 m		
Mooring ID#: DM193		
Deployed Date: 7/11/16		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		

General Comments: 50 m Sontek failed on deployment, CO2 system #32

Buoy Site: 0 165E ADO	CP		
Mooring Operation: Recovery		Mooring ID#: WA014	
Deployed Location: 00-00.95N/165-13.23E		Deployed Date: 10/2	8/14
Recovered Location: 00-00.192N/169-43.84W Recovered Date: 11/30/15			30/15
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: None			
Fishing/Vandalism: None			
General Comments: None			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations

Buoy Site: 0 165E ADCP	Mooring Depth: 4398 m	
Mooring Operation: Deployment	Mooring ID#: WA015	
Deployed Location: 00-00.52N/165-13.45E		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 2S 165E				
Mooring Operation: Recovery		Mooring ID#: DM148		
Deployed Location: 02-00.18S/165-00.41E		Deployed Date: 8/7/15		
Recovered Location: 02-00.30S/164-59.93E		Recovered Date: 7/12	Recovered Date: 7/12/16	
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: Anemometer mast broken, SSC fouled with sea growth				
Fishing/Vandalism: None				
General Comments: Several sensors out of their mount.				
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service	
			Observations	
Anemometer	1/6/16	Low wspd, WDIR off	Mast broken	
1m Salinity	2/5/16	Data high	Fouled	

Buoy Site: 2S 165E TPOS	Mooring Depth: 4471 m	
Mooring Operation: Deployment	Mooring ID#: DM194	
Deployed Location: 01-59.75S/164-58.99E		
Pre-Deployment On Deck Instrument Failures: None		

Sensors/Equipment Lost at Sea: None
Sensors Damaged During Deployment: None
General Comments: None.

Buoy Site: 5S 165E			
Mooring Operation: Recovery		Mooring ID#: DM102	
Deployed Location: 05	-00.83S/165-10.50S	Deployed Date: 10/26	/14
Recovered Location: 0	05-00.75S/165-07.20E	Recovered Date: 7/14	/16
Sensors/Equipment Lo	ost at Sea: None		
Sensors Damaged/Fou	led: Longline throughou	t the mooring	
Fishing/Vandalism: Lo	ongline throughout the m	ooring	
General Comments: S	hackle holding acoustic r	elease missing cotter pin a	and nut.
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations
WDIR	5/16/16	Off	
RH	2/12/15	Saturated	

Buoy Site: 5S 165E	Mooring Depth: 2487 m	
Mooring Operation: Deployment	Mooring ID#: DM195	
Deployed Location: 05-00.74S/165-10.26E		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: DART 52406		
Mooring Operation: Recovery	Mooring ID#: 52406	
Deployed Location: 05-17.58S/165-00.12E	Deployed Date: 10/26/14	
Recovered Location: 05-17.50S/165-00.53W Recovered Date: 7/14/16		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None		
Fishing/Vandalism: None		
General Comments: None		

Buoy Site: 52406	Mooring Depth: 1826 m
Mooring Operation: Deployment	Mooring ID#: 52406

Deployed Location: 05-00.74S/165-10.26E	Deployed Date: 7/14/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 8S 165E/ATLAS/CO2			
Mooring Operation: Recovery		Mooring ID#: QM021	
Deployed Location: 08-01.30S/164-49.68E		Deployed Date: 8/19/	13
Recovered Location: 08-02.16S/164-46.38E		Recovered Date: 7/15	5/16
Sensors/Equipment Lost at Sea: TP500 lost at sea.			
Sensors Damaged/Fouled: Anemometer missing propeller,			
Fishing/Vandalism: Fishing float on buoy, top section severed, longline througut mooring.			hrouout mooring.
General Comments: None.			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
		•	Observations
Rain	6/24/14	Data flagged	
50m Salinity	9/24/14	Data failed	
1m Salinity	12/21/14	Data failed	
Wind	3/9/15	Data failed	Missing propeller
Buoy	9/12/15	No xmits	
TP500	9/12/15	No data	Lost at sea

Buoy Site: 8S 165E	Mooring Depth: 3901 m	
Mooring Operation: Deployment	Mooring ID#: DM196	
Deployed Location: 08-01.51S/164-49.39E	Deployed Date: 7/16/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: CO2 system #111		

Buoy Site: 8S 180			
Mooring Operation: R	lecovery	Mooring ID#: DM141	
Deployed Location: 07	'-59.20S/179-55.31E	Deployed Date: 7/24/15	
Recovered Location: 0	Recovered Location: 07-59.33S/179-55.80E Recovered Date: 7/19/16		
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: None			
Fishing/Vandalism: None			
General Comments: None			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service

			Observations
AT/RH	7/30/15	Data low	
SSC/SST	8/10/15	Erratic	
Buoy	6/28/16	Last xmit, Power	

Buoy Site: 8S 180	Mooring Depth: 5500 m	
Mooring Operation: Deployment	Mooring ID#: DM197	
Deployed Location: 07-59.05S/179-55.98E	Deployed Date: 7/19/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 5S 180				
Mooring Operation: Recovery		Mooring ID#: DM14	Mooring ID#: DM142	
Deployed Location: 04-57.76S/179-53.88W Deployed Date: 7/26/15		15		
Recovered Location: 0	Recovered Location: 04-56.0S/179-52.38W Recovered Date: 7/20/16		0/16	
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: SSC fouled, T50 broken ferrite core.				
Fishing/Vandalism: Topsection severed, plastic mesh in bridle, batter box broken off.				
General Comments: None				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
None				

Buoy Site: 5S 180	Mooring Depth: 5661 m	
Mooring Operation: Deployment	Mooring ID#: DM198	
Deployed Location: 04-57.93S/179-54.16W	Deployed Date: 7/21/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: ATRH 35547 failed on deployment, replaced with boat ride. New sensor		
SN: 39569.		

Buoy Site: 2S 180		
Mooring Operation: Recovery	Mooring ID#: DM143	
Deployed Location: 01-59.40S/179-51.60W	Deployed Date: 7/27/15	
Recovered Location: 02-00.0S/179-49.91W	Recovered Date: 7/22/16	
Sensors/Equipment Lost at Sea: None		

Sensors Damaged/Fouled: None			
Fishing/Vandalism: Longline gear throught mooring.			
General Comments: Sensor T25 and T50 were deployed in wrong order.			
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			
			Observations
TP300	2/7/16	Data missing	Long line

Buoy Site: 2S 180	Mooring Depth: 5339 m	
Mooring Operation: Deployment	Mooring ID#: DM199	
Deployed Location: 01-59.86S/179-51.422W	Deployed Date: 7/23/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: None		

Buoy Site: 0 180			
Mooring Operation: Recovery		Mooring ID#: DM147	
Deployed Location: 00-01.90N/179-55.20W Deployed Date: 8/20/15)/15	
Recovered Location: 00-00.60N/179-56.10W Recovered Date: 7/23/16		23/16	
Sensors/Equipment Lo	st at Sea: None		
Sensors Damaged/Fou	led: None		
Fishing/Vandalism: No	one		
General Comments: N	one		
Site Sensor Failures	Date Data Flagged	Why data failed	Field Service Observations

Buoy Site: 0 180	Mooring Depth: 5391 m	
Mooring Operation: Deployment	Mooring ID#: DM200	
Deployed Location: 00-01.88N/179-55.44W	Deployed Date: 7/24/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 2N 180	
Mooring Operation: Recovery	Mooring ID#: DM144
Deployed Location: 02-00.50N/179-48.0W	Deployed Date: 7/29/15

Recovered Location: 02-01.43N/179-47.60W **Recovered Date:** 7/24/16 Sensors/Equipment Lost at Sea: Anemometer 39166 Sensors Damaged/Fouled: None Fishing/Vandalism: Topsection severed, anemometer and stanchion broke off, blue paint scrape on buoy hull. **General Comments:** None Site Sensor Failures **Date Data Flagged** Why data failed Field Service **Observations** P300 9/12/15 Data too high 10/1/15 Data failed Stanchion broke Wind

Buoy Site: 2N 180	Mooring Depth: 5473 m	
Mooring Operation: Deployment	Mooring ID#: DM201	
Deployed Location: 02-00.38N/179-47.39W	Deployed Date: 7/25/16	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 5N 180					
Mooring Operation: Recovery			Mooring ID#: DM145		
Deployed Location: 04-59.59N/179-53.46W			Deployed Date: 7/30/15		
Recovered Location: (Recovered Location: 05-00.85N/179-53.80W Recovered Date: 7/25/16				
Sensors/Equipment Lo	ost at Sea: None				
Sensors Damaged/Fou	led: None				
Fishing/Vandalism: N	Fishing/Vandalism: None				
General Comments: None					
Site Sensor Failures	res Date Data Why Data Flagged Field Service Observations				
	Flagged				
None					

Buoy Site: 5N 180	Mooring Depth: 5671 m			
Mooring Operation: Deployment	Mooring ID#: DM202			
Deployed Location: 05-00.16N/179-53.61W	Deployed Date: 7/26/16			
Pre-Deployment On Deck Instrument Failures: None				
Sensors/Equipment Lost at Sea: None				
Sensors Damaged During Deployment: None				
General Comments: None				

Buoy Site: 8 N 180					
Mooring Operation: R	Recovery	Mooring ID	Mooring ID#: DM146		
Deployed Location: 08	3-01.10N/179-53.4	6W Deployed D	Deployed Date: 7/31/15		
Recovered Location: (08-00.91N/179-52.	61 Recovered I	Recovered Date: 7/26/16		
Sensors/Equipment Lo	ost at Sea: None				
Sensors Damaged/Fou	led: None				
Fishing/Vandalism: No	Fishing/Vandalism: None				
General Comments: Top section severed, larg knot in Nilspin at 500 m sensor.					
Site Sensor Failures Date Data Why Data Flagged Field Ser			Field Service Observations		
WDIR	12/1/15	Erratic			
ATMP	10/27/15	Data High			

Buoy Site: 8N 180	Mooring Depth: 5960 m			
Mooring Operation: Deployment	Mooring ID#: DM203			
Deployed Location: 05-00.16N/179-53.61W	Deployed Date: 7/27/16			
Pre-Deployment On Deck Instrument Failures: None				
Sensors/Equipment Lost at Sea: None				
Sensors Damaged During Deployment: None				
General Comments: None				

Buoy Site: Drifting Wx buoy 51001				
Mooring Operation: Recovery	Mooring ID#: 2.3D06			
Deployed Location: 24-23.4N/162-07.6W	Deployed Date: 8/23/15			
Recovered Location: 21-53.34N/174-40.87W	Recovered Date: 7/30/16			
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: None				
Fishing/Vandalism: None				
General Comments: Nylon parted approximately 10 m below the chain.				

Buoy Site: Drifting Wx buoy 51002					
Mooring Operation: Recovery	Mooring ID#: 3D90				
Deployed Location: 17-03.33N/157-48.15W	Deployed Date: 2/4/15				
Recovered Location: 17-34.46N/167-29.20W Recovered Date: 8/1/16					
Sensors/Equipment Lost at Sea: None					
Sensors Damaged/Fouled: None					
Fishing/Vandalism: None					
General Comments: Nylon parted in eye-splice just below the fish-bite.					

2.2 CTD Casts Completed

A Sea-Bird 911plus CTD with dual temperature and conductivity sensors was provided by the ship. Temperature and conductivity sensors are calibrated yearly at Sea-Bird and sent in for diagnostics as necessary.

The following outlines the CTD casts completed during the cruise:

CTDs				
Coordinates	Date	Cast #	Comments	
8N 165E	7/7/16	RR1601-01		
5N 165E	7/9/16	RR1601-02		
2N 165E	7/10/16	RR1601-03		
1N 165E	7/10/16	RR1601-04		
0N 165E	7/11/16	RR1601-05		
2S 165E	7/13/16	RR1601-06		
3S 165E	7/13/16	RR1601-07		
5S 165E	7/14/16	RR1601-08		
8S 165E	7/16/16	RR1601-09		
8S 180	7/20/16	RR1601-10		
5S 180	7/21/16	RR1601-11		
4S 180	7/22/16	RR1601-12		
2S 180	7/23/16	RR1601-13		
0 180	7/24/16	RR1601-14		
2N 180	7/25/16	RR1601-15		
5N 180	7/26/16	RR1601-16		
8N 180	7/27/16	RR1601-17		

2.3 Ancillary Science Projects Completed on the Cruise

The following outlines the ancillary science work performed in conjunction with the TAO operations on the cruise:

Pacific Marine Environmental Laboratory (PMEL) Argo Profiling CTD Floats

Eight (8) Argo floats were scheduled for deployment on this cruise. All Argo Float deployments were completed as scheduled.

Questions concerning ARGO Floats should be directed to:

Gregory Johnson, NOAA/PMEL Tel: (206) 526-6806

or

Elizabeth Steffen, NOAA/PMEL

Tel: (206) 526-6747

The following outlines the Argo floats deployed during the cruise:

Argo Floats					
Coordinates	Date	SN#	Comments		
08-25.14N/163-32.13E	7/7/2016	F0616			
08-02.2N/165-08.4E	7/8/2016	F0620			
05-02.2N/164-52.2E	7/9/2016	F0617			
02-00.11N/165-08.52E	7/10/2016	F0616			
1-59.92S/179-51.59W	7/23/2016	F0619			
00-01.67N/179-55.54W	7/24/2016	F0621			
02-01.6N/179-47.9W	7/25/2016	F0615			
19-59.77N/175-13.7W	7/30/2016	F0608			

Atlantic Oceanographic and Meteorological Laboratory (AMOL) Surface Drifting Floats

Sixteen (16) AOML Surface Drifters were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All AOML Surface Drifter deployments were completed as scheduled.

Questions concerning AOML Surface Drifters should be directed to:

Shaun Dolk, NOAA/AOML Global Drifter Center,

Tel: (305) 361-4546 Fax: (305) 361-4436

E-mail: shaun.dolk@noaa.gov

The following outlines the AOML Drifting floats deployed during this cruise:

AOML Drifters				
Coordinates		Date	SN#	Comments
05-02.0N	164-52.2E	7/9/2016	63344710	
02-00.11N	165-08.52E	7/10/2016	63345260	
02-00.11N	165-08.52E	7/10/2016	63345380	
00-00.37N	165-13.48E	7/12/2016	63345270	
00-00.37N	165-13.48E	7/12/2016	63344690	
01-59.72S	164-58.62E	7/13/2016	63345440	
01-59.72S	164-58.62E	7/13/2016	63344720	
05-01.17S	165-09.95E	7/14/2016	63344970	
04-58.872S	179-53.76W	7/21/2016	63345630	
1-59.921S	179-51.599W	7/23/2016	63345470	

1-59.921S	179-51.599W	7/23/2016	63345490	
00-01.67N	179-55.54W	7/24/2016	63345170	
00-01.67N	179-55.54W	7/24/2016	63344760	
02-01.6N	179-47.9W	7/25/2016	63344730	
02-01.6N	179-47.9W	7/25/2016	63345650	
05-00.548N	179-53.624W	7/26/2016	63344700	